DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453

(707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-006164 Address: 333 Burma Road **Date Inspected:** 08-Apr-2009

City: Oakland, CA 94607

OSM Arrival Time: 1830 **Project Name:** SAS Superstructure **OSM Departure Time:** 630 Prime Contractor: American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

Guo Peng and Zhao Chen Sun **CWI Name: CWI Present:** Yes No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

Bridge No: 34-0006 **Component:** Tower and OBG

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Joe Alaniz was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

Bay 5

This QA inspector performed UT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member(s) is/are identified as Bike Path. The weld designations reviewed are as follows:

- 1. BK001-005-001~004
- 2. BK001-005-008~010

Bay 6

This QA Inspector observed the following work in progress:

FCAW welding of weld joint 4B located on PCMK WSD1-DPSA4-15. Welder is identified as Mr. Li Shugia (053609). ZPMC QC is identified as Zhao Chen Sun. The welding variables recorded by QC appeared to comply with WPS-B-T-2233-B-U3-F.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

FCAW welding of weld joint 2A located on PCMK ESD1-DPSA4-15.

Welder is identified as Mr. Lei Weiwen (019006). ZPMC QC is identified as Zhao Chen Sun.

The welding variables recorded by QC appeared to comply with WPS-B-T-2233-B-U3-F.

Bay 14

This QA Inspector observed the following work in progress:

FCAW welding of weld joint 004 located on PCMK CA33B.

Welder is identified as Mr. Wu Wan Yong (050242). ZPMC QC is identified as Shi Lei.

The welding variables recorded by QC appeared to comply with WPS-B-T-2232-Tc-U4b-F.

SMAW welding of weld joint 004 located on PCMK SEG028*.

Welder is identified as Mr. Yang Gen Chen (219188). ZPMC QC is identified as Shi Lei.

The welding variables recorded by QC appeared to comply with WPS-B-T-2233-B-U2-F.

SAW welding of weld joint 006 located on PCMK SEG031*.

Welder is identified as Mr. Wang Lanying (045265). ZPMC QC is identified as Shi Lei.

The welding variables recorded by QC appeared to comply with WPS-B-T-2221-B-L2c-S-2.

Bay 13

This QA Inspector observed the following work in progress:

SMAW welding of weld joint 004 located on PCMK SEG007A.

Welder is identified as Mr. Ren Jinzhu (044772). ZPMC QC is identified as Shi Lei.

The welding variables recorded by QC appeared to comply with WPS-B-P-2114-Tc-U4b-FCM.

Bay 11

This QA Inspector observed the following work in progress:

SMAW welding of weld joint 26A located on PCMK WSD1-FCAS3-2B/C.

Welder is identified as Mr. Wang Jintao (205679). ZPMC QC is identified as Guo Peng. The welding variables recorded by QC appeared to comply with WPS-B-T-2311-B-P3 and WPS-B-T-2311-B-P3.

SMAW welding of weld joint 28A located on PCMK WSD1-FCAS3-2B/C.

Welder is identified as Mr. Chen Kang (206195). ZPMC QC is identified as Guo Peng. The welding variables recorded by QC appeared to comply with WPS-B-T-2311-B-P3 and

WPS-B-T-2311-B-P3.

SMAW welding of weld joint 28A located on PCMK WSD1-FCAS3-2B/C.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Welder is identified as Mr. Chen Kang (206195). ZPMC QC is identified as Guo Peng. The welding variables recorded by QC appeared to comply with WPS-B-T-2311-B-P3 and WPS-B-T-2311-B-P3.

Bay 10

This QA Inspector observed the following work in progress:

FCAW welding of weld joint 7 and 8 located on PCMK NSD1-TL8H/L. Welder is identified as Mr. Yu Chaoye (053869). ZPMC QC is identified as Liu Liang. The welding variables recorded by QC appeared to comply with WPS-B-T-4132.

FCAW welding of weld joint 54 located on PCMK WD1-A22A/B. Welder is identified as Mr. Yu Yonglai (048378). ZPMC QC is identified as Jin Dong Liang. The welding variables recorded by QC appeared to comply with WPS-B-T-2332-Tc-P5-F.

FCAW welding of weld joint 53 located on PCMK WD1-A22A/B. Welder is identified as Mr. Jin Xiaogang (053869). ZPMC QC is identified as Jin Dong Liang. The welding variables recorded by QC appeared to comply with WPS-B-T-2332-Tc-P5-F.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (134-8257-0045), who represents the Office of Structural Materials for your project.

Inspected By:	Alaniz,Joe	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer